### **ENVIRONMENTAL CHEMISTS**

# Analysis For Total Metals By EPA Method 200.8

Client ID:	M02867	
Date Received:	08/21/08	40
Date Extracted:	08/25/08	
Date Analyzed:	08/25/08	
Matrix:	Water	
Units:	ug/L (ppb)	

Client:	Alaskan Copper Works
Project:	PO M02867, F&BI 808222
Lab ID:	808222-01 x10
Data File:	808222-01 x10.037
Instrument:	ICPMS1
Operator	hr

Lower

Limit:

60

Upper Limit:

125

Internal Standard: Germanium	% Recovery: 107
Analyte:	Concentration ug/L (ppb)
Chromium	454
Nickel	432
Copper	435
Zinc	52.8

#### **ENVIRONMENTAL CHEMISTS**

## Analysis For Total Metals By EPA Method 200.8

Alaskan Copper Works PO M02867, F&BI 808222 Client ID: Method Blank Client: Date Received: Not Applicable Project: Date Extracted: 08/25/08 Lab ID: 18-328 mb Date Analyzed: 08/25/08 Data File: I8-328 mb.016 ICPMS1 Matrix: Water Instrument:

Units: ug/L (ppb) Operator: hr

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 96 60 125

Concentration
ug/L (ppb)

Chromium
Nickel
Copper
Sinc
Sinc
Sinc
Since
Si

#### **ENVIRONMENTAL CHEMISTS**

Date of Report: 08/28/08 Date Received: 08/21/08

Project: Metro Self Monitor, PO M02867, F&BI 808222

## QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 808235-01 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Percent Difference	Acceptance Criteria
Chromium	ug/L (ppb)	10.1	10.2	1	0-20
Nickel	ug/L (ppb)	8.90	8.96	1	0-20
Copper	ug/L (ppb)	8.63	8.96	4	0-20
Zinc	ug/L (ppb)	13.3	11.1	18	0-20

Laboratory Code: 808235-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Acceptance Criteria
Chromium	ug/L (ppb)	20	10.1	97 b	50-150
Nickel	ug/L (ppb)	20	8.90	105 b	50-150
Copper	ug/L (ppb)	20	8.63	102 b	50-150
Zinc	ug/L (ppb)	50	13.3	95 b	50-150

Laboratory Code: Laboratory ControlSample

Analyte Chromium Nickel Copper	Reporting Units	Spike Level	Percent Recovery LCS	Acceptance Criteria
Chromium	ug/L (ppb)	20	105	70-130
Nickel	ug/L (ppb)	20	106	70-130
Copper	ug/L (ppb)	20	108	70-130
Zinc	ug/L (ppb)	50	98	70-130

#### **ENVIRONMENTAL CHEMISTS**

## **Data Qualifiers & Definitions**

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com



August 28, 2008

### **INVOICE #08ACU0828-1**

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M02867, F&BI 808222 - Results of testing requested by Gerry Thompson for material submitted on August 21, 2008.

 $_{\text{FEDERAL TAX ID}}^{\text{FEDERAL TAX ID}}(b)$  (6)

200	011 0 1 1	9 8	SAI	MPLE CH	AIN OF C	HS	TO	ĐΥ		17	= .	721	121	10	Χ.		ATO
8000	80822			SAMPLERS	1				{	40	(	101		70	#		AIY
Send Report To JOKE	es VA	tompor	<u> </u>		<i></i>					)			J. F			IAROUN	
Company ALASWAZ	J Copper	1 WO	lks_	PROJECT!	NAME/NO.	m	عہد	tar	,	. 4 4 4	PO# 5280	′ ¬	1 18	KRU!	SH_	(2 Week	<u> </u>
Address 628	S. HANC	one.	20	, 1,00	(	G G	ds			7-10		04		lush (	charg	es author	rized by:
City. State. ZIP	me   zi	A 98	3134	REMARKS							181 186	5				PLE DIS after 30 d	
City, State, ZIP Sept.  Phone # 206-571-6	2Rear # 70	6-382-	1308										] [	Ret	um sa	amples with inst	Š
Thomas and the second s	THE WAY							V.	Ā	MAT	YSES	DEΔ			Cari	VICE HISC	I delicite
				1	+			щ		· ·	In		U EAST	L	Г	T	<del></del>
_		•	70 F			esel	PPH-Gasoline	8021	826	827	18						( <b>4</b> 5
Sample ID	Lab ID	Date	Time	Sample Typ	# of containers	TPH-Diesel	-Gas	y by	la by	Se by	HFS N				-		Notes
ř.					1	TP	ТРН	BTEX by 8021B	VOCs by 8260	Š	(A)		,				
47820 M	101	721/08	11780	40	1.,			7	$\dashv$	+	N	-	-	1			
W. CO 64	10[	70/00	11:00	7760	+ ′			+	+	+	1	<b></b>	-	-		<del> </del>	
					1	Н		-	+	+	+	-	<u> </u>	-	<del> </del>	<u> </u>	
	<u> </u>					H		$\dashv$	+	+	+	-	-		-		7
97 - 1140 - 27 27	<del>_</del>			<b>-</b>				-	+	+	+	-	-	-	-	11, 1	
		() NC	*8		<u> </u>				$\perp$	+	-	-	<u> </u>				
			39.1		-				_	1	_		<u> </u>	-	<u> </u>		· · · · · · · · · · · · · · · · · · ·
»		9" :															
<u> </u>				- 00													
72.5	. 0		aF va						T	T							17
Friedman & Bruya, Inc.	1	SIGNATU	NB	1	PRINT	_	ME			T	Ç	DMF	ANY	1	_	DATE	TIME
3012 16th Avenue West	Retinguished by	A	=	- (0	renald	/ <	14	orga	302	1	A	Co			3	3/21/0	1:48 Pu
Seattle, WA 98119-2029	Received by:	m aw	<u>vo</u>	_ N	nan P	ha	2			1	Fe	B	T_		8	21/05	18.48
Ph. (206) 285-8282	Relinquished by				#. N		1.5			1		ME:					
Fox (206) 283-5044  FORMS\COC\COC.DOC	Received by:				*2	-					-22						

Samples received at 23°€

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

August 28, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on August 21, 2008 from the Metro Self Monitor, PO M02867, F&BI 808222 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures